Building Name Address	Use (as per FSA Annexed Table 1)	Date and Time of Incident	Structure and Stories Area	Extent of Damage (Damaged Area/ Total Area)	No. of Casualties	
W''. C	Mito Central Building	Dec. 26, 1970	Fire resistive 8 stories			
		Breakout at 14:30 (approx)	above ground and 2 below	<u>All</u> , Half, Partial, Small	Fatalities 2	
2-3-2 Izumi-cho Mito,	Complex (16) a	Notified at 14:46 Noticed by fire watchtower	Building area 1,372 m ²	10,476 m ²	Injured	
IDANANI			Total floor	(86%)	18	
		Extinguished by 22:00	area 12,112 m ²	,	()	

I. Summary of Fire Incident

This fatal fire originated from the exhaust air duct of the kitchen on the 1st basement floor of a multi-tenant building that was located in a busy street that was crowded due to the end of year sales. Because of poor fire-safety management, the building was completely destroyed in the daytime and 2 employees died.

	Floo	Total	Domogod	Han (Durnaga)	No. of		atalities	Fire eccens	Eirofiahtina
(2) Co	F100		Damaged	Use (Purpose)		Г	alannes	Fire escape	Firefighting
	1	area m²	area m ²		persons			equipment	equipment
ndi		m²	III z					Inside stairs	48 sets of indoor
(2) Conditions per Floor								(3 sets on B2	fire hydrants Automatic fire detection system Fire extinguishers
	8	251.6		Machine room				floor to 1st, 1 on 1st to 3rd,	
	7	1,372.2	1,372.2	Wedding hall	155			1 on 1st to	
00r	6	1,372.2	1,372.2					7th, 1 on 1st	
	5	1,372.2	1,372.2	Offices	53			to PH1st)	
	4	1,372.2	1,372.2		48			1 escape	
	3	1,372.2	1,372.2	Offices,	61			chute on 7th	
				Department store	► Department	Store	e Portion	1 slow	
	2	1,372.2	1,372.2	Department store	254			descending machine on	
	1	1,313.1	914.7	Department	38			5th	
		,		store, Bank,				2 sets of metal	
				Office				ladders on 5th	
	(B1)	1,328.1	1,328.1	Restaurant	499				
	B2	986.1		Machine room,		2	(1 male, 1		
				Locker room,			female)		
				Electrical room					
	Total	12,112.1	10,476		1,110		2		
(3) Origin of Fire		(Floor, Room, Part, Combustibles, Habitable/Non-habitable				(4)	Unknown		
	Room	Rooms, Present/Absent)) Cause	CHRIOWII		
rigii	_								
0	From the exhaust air duct of the restaurant kitchen on the 1st					e o			
Ę;	basement floor					of Fire			
ė.	5				ē				

(Location of Fire Source) (Propagation from Source) (Propagation to Other Floors) (Propagation to Adjacent Bldg) (5) Fire Propagation Path From the duct Spread to the 1st floor through The exhaust air duct From the windows of to the ceiling the stairwell with no fire of the restaurant the fire building to the compartment, and to the upper kitchen on the 1st adjacent building floors from the open ceiling, through a ventilation basement floor stairwell and vertical shaft The fire emerged from the exhaust air duct of the restaurant kitchen on the 1st basement floor and spread to the ceiling. The nearby stairs leading to the 1st floor were not fireproofed and the fire spread via these stairs to the sales floor of the 1st floor, before spreading higher to the 3rd floor through the open ceiling area. In addition, via the stairwells and clearances around the duct and pipe shafts, which were not properly fireproofed, the fire spread to the top floor. Notably, the bank on the 1st floor was perfectly fireproofed and therefore, the fire did not penetrate into the bank. O Main Reasons for Propagation of the Fire ° The employees tried to extinguish the fire but the fire was beyond their control because it had reached the backside of the ceiling and therefore the fire propagated further. There was no fire compartment (horizontally and vertically) and fire doors were left open for the evacuation. O Smoke Propagation Path The smoke that was produced in the kitchen spread in all directions and rapidly ascended the stairwells and elevator shaft that acted as a chimney. In addition, the smoke traveled continuously to each floor through the duct and clearances of the electrical/bathroom piping systems. II. Summary of the Building (1) Built Construction, Completion, and Major Renovations (Completion) September 1964 (2) Vertical Shafts Fire Prevention Management (3) Fire Prevention Stairs **Duct Spaces** [X][X] No fire-prevention manager. Elevators [X] Pipe Shafts [X] No fire defense plan. Escalator Other (garbage chute) O No cooperative fire safety management. O No fire drill. o The clearances of the electrical wires and the No voluntary inspection. ducts that were running directly from the 2nd O Security patrol by 2 guards in the daytime and 4 guards at basement to the 7th floor were not sealed off. nighttime. On the stairwell, the fire doors were left open (for evacuation), and above the fire doors, the backside of the ceiling was not compartmentalized. (4) Fire Compartments (5) Firefighting Equipment The open ceiling running from the 1st to 3rd floors O The alarm sound was turned off on the control panel of the on the department store floor had no fire automatic fire detection system; therefore, no one heard any compartment for the 1,500 m² area. alarm when the fire broke out. • The guiding lights and the emergency alarm system were not installed in their proper places. O During the fire, the fire escape equipment on the 5th and 7th floors was not utilized.

III.	Actions Taken a	after the Fire was Detected					
(1) First Detected	Detected byHow and whAction taker	y (He found flam	(A staff member of the restaurant kitchen where the fire broke out) (He found flames after being alerted by an unusual sound) (He shouted "Fire!" and tried to extinguish the fire)				
tected	Around 14:30, when the kitchen staff member was washing dishes at the restaurant in the 1st floor basement, he heard a crackling sound coming from near the rice cooker behind him. He saw a growing flame, 50 cm in diameter, on the rice cooker chimney and the ceiling around the chimney, and shouted "Fire!" to alert people nearby.						
(2) Emer	Emergency Call Yes [X] (Receptionist on the 1st floor) Time elapsed since the discovery (17) minutes No []						
2) Emergency Call	 Around 14:46, a watchtower guard saw black smoke arising from the rooftop of the Shimazu Department Store that was located next to the Central Building, and he notified a watchtower operator. The operator called the Department Store; however, the Department Store answered that everything was fine. In the meantime, the watchtower guard reported again "The black smoke is getting worse". Shortly after, a female called them and said, "The restaurant M in the basement of the Central Building is on fire". The repairman of the Central Building noticed the fire and told the receptionist on the 1st floor to make a direct emergency call, which she did. 						
(3) Initial Firefighting Activities	<u>Initiated</u>	Successful [] Failed [X] Comparison of Extinguished timing Comparison of Firefighting difficulties Comparison of Extinguished C	[] [X] []	(Reasons or Conditions) The restaurant staff immediately tried to extinguish the fire with water and fire extinguishers. At first it seemed that this had succeeded, but the flames emerged again from the ceiling of the hallway. They fought the fire with a hose that extended from the indoor fire hydrant, but they had to evacuate because of the			
	Not Initiated	Extinguished timingFirefighting difficultiesFirefighting methodOther	[] [] []	intense flames, heavy smoke, and power outage.			
(4)	(Obstacles or Difficulties in Fire Control)						
) Summary of Firefighting Activities	By the time firefighters arrived, black smoke was pouring out of each floor above the 3rd floor and many people were trapped inside the building. Most of the firefighters entered the building for the search and rescue activities rather than firefighting activities.						

(5)	Means of Escape (No. of Persons)	Obstacles to Evacuation		
Evacuation		 No windows [] Barred openings [] Locked emergency doors (Exits) [] Alarm system [X] (Poorly controlled, Malfunctioned, Not installed) Power outage [] Other [X] 		


- At the early stage of the fire, people (employees and visitors) who were in the 1st basement to 3rd floors were able to get out soon after they became aware of the fire.
- The office workers who were on the 3rd to 5th floors slowly noticed the fire and most of them escaped through the central stairs filled with smoke. A few people were trapped, but they used ropes to climb down from the window or were rescued by a ladder truck and the firefighters' escape chutes.
- On the 6th and 7th floors, there were 2 groups of wedding-party guests and hall staff. One group noticed the fire relatively early and was able to descend via the stairs. The other group noticed it later and became trapped on the 4th floor, where they were rescued by firefighters. A few people were trapped in a kitchen on the 7th floor and in a break room on the 6th floor, but they used a rope to descend to the rooftop of an adjacent building.

Healthy individuals 2 (Drunk persons) Individuals in need of assistance Infants Elderly Handicapped Patients/ill persons Obstacles to Evacuation No windows [] Barred openings [] Locked emergency doors (Exits) [] Alarm system [X] (Poorly controlled, Malfunctioned, Not installed) Power outage [] Other [X]


The 2 fatalities in this fire were a male employee Y and a female employee S. Y (age 32) went to the 2nd basement floor to turn off the power in the electrical room and at the door, somebody told him that the power was already turned off, but he went inside to confirm. On the way back to the 1st floor, he met S (age 18) in the dark and they tried to escape together. However, they were trapped because the upper floor was already in flames. Y helped S to go to the break room and called for help through the internal telephone. The firefighters went to look for them according to the information given to them in the telephone call, but they could not find them. S was a student and part-time worker who just started working there that day. How she ended up in the basement before meeting Y is unknown.

IV. Issues and Lessons Learned


- 1. Building management had not instituted any fire safety management system. There was no chief fire-prevention manager because not even individual tenants had a fire prevention manager.
- 2. The alarm sound system was turned off on the control panel and this resulted in late detection of the fire and delay in subsequent responses such as evacuation and incipient-stage fire control.
- 3. There were many building code violations. The open ceiling running from the 1st to 3rd floors in the department store floor had no fire compartments for an area of 1,500 m². The clearances of electrical wires and duct spaces that ran directly from the 2nd basement to the 8th floors were not sealed off. The fire shutters for each stairwell remained open. The backside of the ceiling above the fire doors had defective openings.
- 4. Until the firefighters arrived, construction workers from a nearby construction site and neighbors helped many people to escape by using ropes and metal ladders, and they continued to help even after the firefighters arrived.



Central stair Elevator



1st basement floor



2nd basement floor