| Building Name Address | Use (as per FSA Annexed Table 1) | Date and Time of Incident | Structure and Stories Area | Extent of Damage (Damaged Area/ Total Area) | No. of Casualties |
|------------------------------|---|---------------------------------|---|--|----------------------|
| | | Nov. 23, 1975 | Fire resistive | | |
| Shuwa Mejirodai Residence | Apartment building | Breakout at 02:07 (approx.) | 11 stories above ground and 0 below | All, Half, Partial, Small | Fatalities 2 |
| 1210 | (5) b | Noticed at 02:12 Notified by | Building area 2,409.04 m ² | 314 m ² | Injured |
| Kunugidamachi, | (0) 5 | emergency call | Total floor | (1.2%) | Injured 19 |
| Hachiohji ,TOKYO | | Extinguished by 04:22 | area 25,702.86 m ² | | (2) |

I. Summary of Fire Incident

) Summai

Around 02:00, there was an explosion in Room 614 on the 6th floor of the apartment building. Because of the impact of this explosion, the floors of the 6th and 7th floor crumbled into the 5th floor and fire spread to these floors instantly. The blast wave also deformed the doors of other rooms. This fire resulted in 19 injuries and 2 fatalities, including 1 fatality on the top floor (11th floor). This fire-resistive apartment building was constructed by the HPC method in the shape of a U that had two wings extended from the north side of the main portion.

| (2) | Floo | Total | Damaged | Use (Purpose) | No. of | No. of | Fire escape | Firefighting |
|----------------------|-----------|----------------|----------------|-----------------|---------|------------|---------------|------------------------|
| Ω | r | area | area | . , , | persons | fatalities | equipment | equipment |
| ondit | | m ² | m ² | | | | 2 sets of | Emergency alarm |
| ion | RH | 73.62 | | | | | outside | system (Bell) |
| (2) Conditions per F | 11 | 2,322.02 | | Apartment house | | 1 | escape stairs | Water pipe connections |
| Floor | 10 | 2,322.02 | | IJ | | | | |
| ř | 9 | 2,322.02 | 62.7 | IJ | | | | Emergency |
| | 8 | 2,322.02 | | IJ | | | | equipment |
| | 7 | 2,322.02 | 62.7 | IJ | | 1 | | Fire extinguishers |
| | (6) | 2,322.02 | 125.4 | IJ | | | | Water outlet |
| | 5 | 2,322.02 | 62.7 | IJ | | | | |
| | 4 | 2,322.02 | | IJ | | | | |
| | 3 | 2,322.02 | | IJ | | | | |
| | 2 | 2,322.02 | | IJ | | | | |
| | 1 | 2,409.04 | | 11 | | | | |
| | Tota I | 25,702.8 6 | 313.5 | | | 2 | | |

) Origin of I

(Floor, Room, Part, Combustibles, Habitable/Non-habitable Rooms, Present/Absent)

From Room 614 in Building B

One male occupant (age 31) was in this 3-bedroom unit when the fire broke out. The rooms were constructed with a wooden frame and fabric-wallpapered plywood.

Gas explosion (utility gas)

Presumably, the occupant connected the hose of a portable gas burner to the outlet to cook *Sukiyaki*, but he decided to stop because he did not have enough ingredients. He unplugged the hose from the outlet and he thought that he closed the valve at that time. However, he actually turned the valve the wrong way, leaving the valve "open" after he went to bed. As a result, some fire source ignited the leaked gas causing the explosion.

| (5) Fire Propagation Path | (Location of Fire Source) (Propagation from Source) Room 614 Gas explosion | (Propagation to 4 different directions (upper, lower, left and right) (Propagation to 9th Floor) Collapsed or cracked floors and ceilings due to the blast wave | | | | |
|--|--|--|--|--|--|--|
| | Because of the explosion, the floor and ceiling of the eat-in kitchen collapsed completely and the units directly above and below the fire unit were engulfed in flames. The fire spread to both units on the left and right side of the fire unit because the blast brought down or cracked the walls. From the 6th to 9th floors, the flames that emerged from each room to the outside balcony became one large flame and formed into an arch. Because of this shape, the fire jumped across the 8th floor and ignited a unit on the 9th floor. | | | | | |
| | O Main Reasons for Propagation of the Fire The explosion caused the walls, ceilings, and floors to collapse. After the leaked gas ignited, fire spread instantly. The residual gas in the gas line also leaked eventually and facilitated the fire spread. Because of the unique shape of the building, the fire room was located in a blind spot. Because of this, the firefighters had difficulty in spraying water and controlling the fire effectively at first. | | | | | |
| | O Smoke Propagation Path o Along with the fire, smoke traveled through the collapsed portions of the floor, ceiling, wall, and broken glass window. | | | | | |
| II. Summary of the Building | | | | | | |
| Construction, Completion, and Major Renovations (Building confirmation) October 20, 1971 (Inspection upon completion) January 19, 1973 | | | | | | |
| Ξ: | (2) Vertical Shafts | (3) Fire Prevention | | | | |
| Fire Preventio | Stairwell [X] Duct space [] Elevator [X] Pipe Shafts [] Escalator [] Other () [] | The building had a fire-prevention manager as required and had submitted the paper work to the local fire station. Building management had created and submitted a fire | | | | |
| n Management | The maintenance was adequate. | defense plan to the local fire station. No practical fire drills were conducted. | | | | |
| | (4) Fire Compartments | (5) Firefighting Equipment | | | | |
| | Fire compartments for each of the units | Good | | | | |

| III. | III. Actions Taken after the Fire was Detected | | | | | | |
|---|---|--|--|--|--|--|--|
| (1) First Detected | Oetected by How and who Action taken | w and why (Sound and impact of the gas explosion) | | | | | |
| ed | (The occupant | and his neighbors instantly realized the | ere was a fire because of the impact of the explosion) | | | | |
| (2) Em | Emergency Call | Yes [X] (The occupant of Room 1119 Building B) No [] | 9 in Time elapsed since detection () minutes (Explosion) | | | | |
| 2) Emergency Call | As soon as occupant K (age 34) who was asleep in his unit, Apartment 119 of Building B, heard the blast, he instinctively thought that it was an explosion and made a 119 call from his room without looking outside. | | | | | | |
| (3) Initial Firefighting Activities | | Successful [] Failed [] | (Reasons or Conditions) | | | | |
| | Initiated | Extinguished timing [] Firefighting difficulties [] Firefighting method [] | The explosion caused the floor, ceiling, and wall to collapse and the occupant in the fire room fell to the lower floor along with the fire. This happened all at once and spread the fire, so firefighting was not the first thing residents were concerned with. | | | | |
| Activities | Not Initiated | Extinguished timing [] Firefighting difficulties [] Firefighting method [] Other [] | | | | | |
| (Obstacles or Difficulties in Fire Control) | | | | | | | |
| (4) Summary of Firefighting Activities | o Firefighters could not set the ladder portion of the aerial ladder truck directly onto the building because the main street was too narrow for the ladder truck to come close enough and the building layout was too unique. Therefore, it took a long time for them to set up the water firefighting activities and they eventually sprayed water from the ladder instead of attacking the fire inside directly. | | | | | | |
| refigh | Since the cause of the fire was an explosion, people could not make effective use of the firefighting equipment, which slowed the fire control activities. | | | | | | |
| ting Act | Since the building was large and many people lived there, the lack of information confused the firefighters in their assessment of the situation. | | | | | | |
| ivities | o The firefighters had difficulty reaching evacuees because there were many rooms on each floor. | | | | | | |

| (5) | Means of Escape (No. of Persons) | | Obstacles to Evacuation | | |
|-----------------|---|-----------------------------|--|--|--|
| (5) Evacuation | Stairs [X] (most of the occupants) Elevators/Escalators [] () Escape equipment [] () Directly to the ground from windows or Rescued [X] (2) Other () [] () | openings[]() | No windows [] Barred openings [X] Locked emergency doors (Exits) [] Alarm system [] (Poorly controlled, Malfunctioned, Not installed) Power outage [] Other [] | | |
| | Most of the occupants could exit from their units through hallways and stairs, but some occupants evacuated differently: From the window of the bathroom because the entrance door was deformed. (9 occupants in Rooms 713 and 914 From the entrance door of the neighboring unit by breaking down the partition wall on the balcony because of smoke in their own units. From the window (no iron bars) of the unit because the entrance door was deformed. (2 occupants of Room 1114) Rescued by firefighters. (2 occupants of Rooms 814 and 1114) The male occupant of the fire room fell into Room 514, and with the help of the occupants of that room, they escaped to Room 515 via the balcony. | | | | |
| (6) Causalities | Healthy individuals 2 | 1 | | | |
| | | | oors (Exits) [] oorly controlled, Malfunctioned, Not installed) | | |
| | A female occupant (age 21) who was asleep in the 4.5-tatami room of Room 714 was trapped by the growing flames and died because her kitchen floor collapsed and her window was protected by iron bars. In Room 1114, a family of 4 were sleeping. Their entrance door was deformed and the man and his oldest daughter barely escaped via the window, but his wife (age 31) and youngest daughter (age 3) were trapped. They were rescued by firefighters, but the wife died of carbon monoxide poisoning. | | | | |
| IV. | IV. Issues and Lessons Learned | | | | |
| <u> </u> | Total and Loop in Louisian | | | | |
| | | | | | |
| 1. | The explosion caused the 6th and 7th flo | oors to collapse and the fi | re to spread quickly to Rooms 514. 614. and 714. | | |

- 2. Many occupants were trapped by the deformed doors and the barred windows facing the hallway. This made the evacuation difficult and resulted in many casualties.
- 3. When designing a high-rise apartment building, the designer should plan for effective street width or open space on the side of the building so that an emergency vehicle (ladder truck) can access the building effectively.
- 4. In this fire, the ladder truck operation was hampered by parked cars and utility poles on the street.



